



# Service bulletin

C204

THE BRITISH MOTOR CORPORATION (AUSTRALIA) PTY. LIMITED

FOR THE ATTENTION OF SERVICE AND PARTS MANAGERS

CARS


## FRONT SEAT ADJUSTER STOP.

To prevent the possibility of pushing the left hand seat adjuster wheel off the rear of the front seat riser, A front seat adjuster stop - HYB0860 has been introduced for a service fix. An adjuster stop will be incorporated in Production.

AUSTIN  
FREEWAY

Attachment of stop is by 2-off No.8 x 3/4" flat head countersunk zinc plated self tapping screws - CTZ806 - in place of the existing parts used for attachment of the wear strip and located in the holes provided.

N. Prescott  
Service Manager.



8

22/8/62

Page 1 of 1