



Service bulletin

C. 217
E. P. 4

THE BRITISH MOTOR CORPORATION (AUSTRALIA) PTY. LIMITED

FOR THE ATTENTION OF SERVICE AND PARTS MANAGERS.

COOLING SYSTEM

Attention is drawn to the method of fitting the thermostat to the "B" Six cylinder engine, as the method outlined in the Workshop Manual Part No. T.P.654, page C.4 Fig. C.4 is not correct.

The Thermostat must be replaced as shown in the sketch with the spring at the base of the thermostat.



Attached herewith are two illustrations for insertion into your Workshop Manual. Please cut out and paste over the existing illustrations to correct your copy.

All current stocks of the Workshop Manual have been corrected. Should you require additional illustrations to correct your stock, please contact the Service Department, Technical Publications.

N. Prescott

N. Prescott
Service Manager

CARS

AUSTIN

FREEWAY

STATION

WAGON

WOLSELEY

24/80

Page 1 of 1

S

10.1.63