



# Service bulletin

C  
230  
EXPORT  
8

THE BRITISH MOTOR CORPORATION (AUSTRALIA) PTY. LIMITED

FOR THE ATTENTION OF SERVICE & PARTS MANAGERS.

## HEAVY CLUTCH PEDAL EFFORT

To alleviate the condition of heavy clutch pedal operation on these models, a clutch master cylinder, having a larger bore and longer push rod, has been fitted at the following approximate Car Serial No:-

Austin Freeway Saloon	YAABS1/5783
Austin Freeway Station Wagon	YABW1/4157
Wolseley 24/80	YWBS1/5654

If heavy clutch operation is reported in the field on vehicles prior to the above numbers, a 'Service Fix' is available by fitting the following kit: HYL.2737, available through normal parts channels.

The kit contains 1 off Clutch Operating Cylinder AYB.5068  
1 off Push Rod - Clutch Master Cylinder AYB.5069

NOTE: The new dimensions for clutch pedal travel is  $5\frac{3}{8}'' - \frac{1}{4}''$  instead of  $4\frac{1}{2}''$ .

N. Prescott  
Service Manager

CARS

AUSTIN

FREEWAY

SALOON

STATION

WAGON

WOLSELEY

24/80

S

15.5.63

Page 1 of 1