




Service bulletin

C
235
EXPORT
9

THE BRITISH MOTOR CORPORATION (AUSTRALIA) PTY. LIMITED

FOR THE ATTENTION OF SERVICE & PARTS MANAGERS.

BRAKE PIPE POSITION



Instances have been reported of the brake pipe Part No. 1H215 positioned between the five way connection and L/H front brake hose lying too close to the rear of the engine. Also the brake pipe Part No. 1H5717 laying too close to the starter motor and gearbox mounting plate.

Vehicles in Service should be examined immediately and if the clearance is not sufficient to stop chafing, the pipes should be repositioned by a slight pressure at suspect areas.

Arrows in sketch show pipes which may require attention.

N. Prescott
N. Prescott
Service Manager.

CARS

AUSTIN

FREEWAY

WOLSELEY

24/80

S

22.5.63

Page 1 of 1